


RadMaster® Quick Reference Guide



Press to view additional parameters

Press 6 🖦

to view additional setpoints

to change field value.


15°C

Mode

Revision: 16.00.00; Doc Number: CC-RM-QRF



Sensor Operation



Revision: 16.00.00; Doc Number: CC-RM-QRF

scheduled ON.